


OKI MC562w Example - Show Network Configuration Guide

Use these instructions if ActKey cannot communicate with the scanner or if the printer IP address changed.


Step 1

Double click the ActKey icon on the desktop.



Step 2

On the Windows taskbar near the time clock, click the UP ARROW to show hidden icons.



Step 3

Right click the small ActKey icon in the hidden icons area.

Step 4

Select Show Network Configuration.

Step 5

Select Scanner.

Step 6

Select Edit Scanner.

Step 7

Enter or update the printer IP address and save the changes.

Important: If the printer is set to Auto IP Address, the printer IP address may change after a reboot or network change. Updating the IP address in ActKey usually resolves the communication problem.